MARYLAND GEOLOGICAL SURVEY Merryman Hall The Johns Hopkins University Baltimore, Maryland 21218 (301) 235-0771

bench mark:

COUNTIES (MD/PA)	WASHINGTON/FRANKLIN
M&D milestone no.	94 (97)
MHT-HSI no.	WA-IV-094
	•

PROTECTED ENDANGURED/MDSSJING

FIELD SHEET: MASON & DIXON LINE, MARYLAND-PENNSYLVANIA BOUNDARY MARKER SURVEY

LOCATION: USGS 7.5 quadrangle Smithsburg 1953 971 UTM 18.28060.439955 bench mark/date none observed original site/MonWood/date 1767 Off N/S Midvale Road/MD 418, Ringgold, MD vicinity. About 0.8 mile NNE of center of settlement of Ringgold; about 1800' NW of Worthington farmhouse & barns; about 2400' E of MD 64/PA 997; in the middle of a level "island" of deciduous woods surrounded by Worthington farmed fields. Cannot be seen from any rd or farm lane. DIRECTIONS TO SITE: From M&D 93 (96): continue on Harbaugh Church Rd W about 500' to its end at MD 418/ Midvale Rd; turn left (S&W) & follow about 0.9 mile to private drive leading to Lee Worthington farmhouse (N/S); turn right (N), drive to house & request (over) DESCRIPTION/MEASUREMENTS: original/replication date 1767; squared oolitic DESCRIPTION/MEASUREMENTS: original/replicative replacement/ date 1707; squared object of the stone post, standing about 1' above ground; P on N/S, M on S/S

N face (PA): 10½" wide x 12" high; P intact, circle panel discernible, fluting & margins gone; surface scarred; chips all edges & corners

E face: 12" wide x 12" high; some fluting no margins remain; vertical gouge in center; chips all edges & corners

S face (MD): 10¾" wide x 13½" high; M clear but chipped, circle panel nearly intact; some fluting no margins remain; big chips SE corner & side edge

W face: 12¼" wide x 13½" high: most fluting no margins remain; bullet hole 12/4" wide x 13" high; most fluting no margins remain; bullet hole
NW edge; chips all edges & corners
planes gone, large shallow depression in center; chips all edges & W face: top:

CONDITION OF MARKER/FOUNDATION: EXCENDENT/good/from/deteriorated/rukus/unexpressed 1900-03 Resurvey notes (order no. 97), as in MGS Vol. 7, 1908, p. 89 97. Milestone No. 94, M. & D., 1767.

corners, especially SE & NW corners; badly weatherworn none indicated on maps; none observed

1950 Inspection notes (present order no. 95, photo no. 94) as in Bayliff, 1959, Appendix C, p. 104

97. Original monument in solid foundation; chipped on all corners and top, worst being northwest and southeast corners. Lettering badly damaged, especially "M" 1979-81 Inspection notes: order no. 94 (97); photos/negatives/slides no.94 (97) 94 (97). Original M&D milestone of 1767 in place, in good condition, firmly set. Letters distinct, but M chipped; chips all edges and corners, especially

northwest and southeast; weatherworn. Protected by site.
SURROUNDING PROPERTY OWNERS (MD/PA): names, addresses, phones

MD: tax map 13, block , P.24 , deed 634 / 362, acres 25.09 Lee B. Worthington. Route 3. Box 318, Smithsburg, MD 21783

Lee B. Worthington, Route 3, Box 318, Smithsburg, MD 21783 (Smithsburg) Phone: 301/824-7542 tax map block P. deed

PA: tax map , block , P. , deed / , acres Lee B. Worthington

RECORDED BY: names, addresses, phones, dates Alice Martin 11/22/80
14308 Mount Ave., Phoenix, MD 21131 Phone: 301/472-2128
Assisted by Clyde E. Martin

Also see: reverse side X , B&W photos X , negatives X , color slides X , maps X , MHT-HSI form , other

DIRECTIONS TO SITE, continued

permission to inspect stone. Park & walk in northwesterly direction about 1800' to stone, following farm service lane & into woods island along path from S end. Stone is about in the middle of this woods, at the W edge of the path.

NOTES

Because we happened to approach this site after recording M&D 95, we inquired about best access to site at the first house S of the Line (E/S) along MD 64. The residents suggested we leave car at their place, hike along S edge of orchard over top of ridge, and head on down to the patch of woodland--far enough away from the Worthington farmhouse and buildings that they thought no one would mind. We did this because it was late afternoon and we didn't want to bother the Worthingtons at suppertime. But any future inspection should be done only with permission of Worthingtons.

B&W PHOTOS/NEGATIVES

5x7 NW corner (1981.2.2), Alice Martin 11/22/80

5x7 SE corner (1980.33.34), "

31/2x5 View SE of stone & setting (1981.2.3), Alice Martin 11/22/80

31/2x5 View NNW of stone & setting (1981.2.4), "

3½x5 Distant View SE toward woods"island" & Worthington farm buildings, (1981.2.7), Alice Martin 11/22/80

COLOR SLIDES

2x2 SE corner (1980.32.36), Alice Martin 11/22/80

2x2 NW corner (1981.1.2), "

2x2 View SE of stone & setting (1981.1.4), Alice Martin 11/22/80

2x2 Distant view SE toward woods "island" & Worthington farm buildings, (1981.1.6), Alice Martin 11/22/80

MAPS

USGS 7½' topographic quadrangle section 1900-03 Resurvey engineer's map (Plate XXXVI), updated MD tax map section

OTHER



Más RATE 094

MASEN EUXUN WESTLINE! MILESPONE 94 (49) SE CORNER (M/-)

PHOTO: ALICE MARTIN (1980, 33. 31 1/22/80



MEN SE TOWARD WOODS (STONE IN CENTER OF WOODS) EWORTHING TON FART BUILDINGS
PHOTO: ALICE MARTIN (1981. 2.7) 11/22/80

MES



MARNIDIXON WE TILE MILE TILE IN 9-1

NU CONICE E 2 - 1

MOD, ALICE MARTIN (192. 2. 2) 11 22/10



HED DEST LINE; MILESTONE 94 (97)

VIEW OF STONE & SETTING, LOCKING NNW
ALONG WOODS PATH

PHOTO: ALKE HARTIN (1981. 2.4) 11/22/80



HED WEST LINE; MILEGTONE 94 (97)
VIEW OF STONE 2 SETTING, LOOKING—SE
TOWARD WORTHINGTON FARM
PHOTO: ALICE MARTIN (1981.2.3) 11/22/80

wil



